


RU60170303


RU63715005




RU60220401

RU64602021

RU60140407





RU49810009  
RU47807100




RU62406022

RU49704090

RU60210304








RU65011073



RU65011074

	+		
<ul style="list-style-type: none"> <li>- ALLA FINE DEL LAVORO PROVVEDERE ALLA IMMEDIATA RICARICA DELLE BATTERIE.</li> <li>- AT THE END OF WORKING OPERATION, PROVIDE FOR IMMEDIATE BATTERY RECHARGE.</li> <li>- A LA FIN DU TRAVAIL, PREVOIR LA RECHARGE IMMEDIATE DES BATTERIES.</li> <li>- NACH ARBEITSENDE FÜR DIE SÖFORTIGE BATTERIELADUNG SORGEN.</li> <li>- AL FINAL DEL TRABAJO PROVEER A LA RECARGA INMEDIATA DE LAS BATERIAS.</li> </ul>			
	+		
<ul style="list-style-type: none"> <li>- PER IL FERMO MACCHINA SUPERIORE A DUE SETTIMANE, STACCARE I CONNETTORI.</li> <li>- WHEN THE MACHINE IS STOPPED FOR MORE THAN TWO WEEKS, TAKE OFF THE CONNECTORS.</li> <li>- ARRÊT DE LA MACHINE SUPÉRIEURE À DEUX SEMAINES, DÉBRANCHER LES CONNEXIONS.</li> <li>- BLEIBT DIE MASCHINE MEHR ALS ZWEI WOCHEN IM STILLSTAND, DIE STECKER TRENNEN.</li> <li>- CUANDO LA MAQUINA ESTÁ PARADA POR MÁS DE DOS SEMANAS, DESCONECTAR LOS CONECTORES.</li> </ul>			

RU65001098



RU65011047